

No : 02 / 2020
Date : 07 July 2020
Rescission Date : N.A



AIRPORT EMERGENCY SERVICE

FIRE PREVENTION CIRCULAR

To All CAG's Tenants

RECOMMENDATION TO REPLACE ALL MAGNETIC BALLASTS TO SAFER ELECTRONIC BALLASTS

- We will like to recommend for all tenants to replace all magnetic ballasts in lighting fixtures to the safer electronic ballast for your own safety.
- 2 Over the past few years, there were a few instances of fires resulting from lighting equipment failures and after investigation, faulty magnetic ballasts were the likely cause.
 - 3 To safeguard life safety of all staff, passengers and members of public, it is highly recommended for all tenants to replace any old magnetic ballast installation with approved electronic ballast or to replace their lighting setup with LED lights from reputable/approved sources.
 - 4 For further clarifications, you may contact the Fire Prevention (FP) of the Airport Emergency Service at 6541 2535 or e-mail to: fire.safety@changiairport.com.

A handwritten signature in black ink, appearing to read "Addison Low".

ADDISON LOW
Head, Fire Prevention Section
Airport Emergency Service