

No : 03 / 2021
Date : 31 May 2021
Rescission Date : NA



AIRPORT EMERGENCY SERVICE

FIRE PREVENTION CIRCULAR

To All Renovation Contractors

COMPLIANCE WITH SS 650 -1:2019 CODE OF PRACTICE FOR TEMPORARY ELECTRICAL INSTALLATIONS

There was a case of fire incident involving a temporary distribution board at a renovation site in Changi Airport.

2 AES would like to send a strong reminder to renovation contractors to ensure strict compliance with SS 650-1:2019 Code of Practice for Temporary Electrical Installations. SS650-1:2019 stipulates that all temporary electrical installations shall be inspected by a skilled person at least once a month. Upon completion of the inspection, the skilled person shall complete and sign the 'Temporary Electrical Installations Inspection Checklist for Construction and Building Sites'.

3 AES requires all existing renovation sites to submit, by 4 June 2021, the inspection checklist for the period of December 2020 to May 2021 to the respective CAG Project Officer in Charge.

4 For further clarifications, you may contact the Fire Prevention Section (FPS) of the Airport Emergency Service at 6541 2535 or e-mail to: fire.safety@changiairport.com

A handwritten signature in black ink, appearing to be "Addison Low".

ADDISON LOW
Head, Fire Prevention Section
Airport Emergency Service